

In the drawings:

In FIG. 1, add two connections from MOSFET bridge 6 to multi-trip transformer circuit 4 as shown in red ink.

In FIG. 3, add reference designator 56b and accompanying lead line as shown in red ink.




Fig. 1




Fig. 3